Fluke 3540FC Firmware Release Notes

V1.6

Date: September 14, 2020

Improvements:

- Security Update - changed transport layer security.
  <u>Please update your instrument early in order to maintain connectivity.</u>
- Removed orphaned functionality.
  Previous releases came with an option to copy logging data to USB mass storage devices, where copied data could not become processed in any way. This option has been removed for clarity.

V1.5

Date: February 15, 2018

New Features:

- Added feature for support Wi-Fi captive portals with web browser interface when selecting SSID for remote monitoring.

Improvements:

- Improved speed of downloading a long local logging session.
- Improved USB functionality so that when USB drive is connected a dialog will be shown to allow copy of logging sessions to USB.
- Corrected touchscreen keyboard layout to include #, {, }, |,\ ` characters.
- Corrected communication protocol to allow the FC app to prompt the user to end the session before downloading.
- Corrected issue that would show a grey Start Monitoring button when current clamps was removed.
- Changed USB product ID to allow communications with same driver for different types of Fluke Power Quality products on the same PC.